

BLDGS EDIT-Z235B259  
 FALL DATA 2012  
 RUN DATE 12/03/2012  
 PAGE NUMBER 1

L.T.C.-HUEY P. LONG  
 BRANCH  
 PARISH  
 RELATION OTHER

ERRORS

NO.	-----B U I L D I N G----- NAME	STATUS & STATE ID	-----SQFEET NET	AREAS----- GROSS	-----DATES OF----- CNST RENOV.	BOOK VALUE-- BLDG. (000)	--REPLACE. V/BLDG. (000)	NO. OF FLOORS
O	EB00 CLTC Huey P. Long	OWNED BY INST. SATISFACTORY	22,256	53,000	2012	11,500	1,150	10
	EE00 CLTC Rod Brady Cam	OWNED BY INST. REMODELING-A SO5971	11,617	16,638	1984	807	1,490	10

BLDGS EDIT-Z235B259  
FALL DATA 2012  
RUN DATE 12/03/2012  
PAGE NUMBER 2

L.T.C.-HUEY P. LONG  
BRANCH  
PARISH  
RELATION OTHER

D E S C R I P T I O N A N D S U M M A R Y O F E R R O R S

ERROR A	DUPLICATE BLDG	
ERROR B	DUPLICATE SUPPLEMENT	
ERROR C	UNMATCHED BLDG	
ERROR D	UNMATCHED SUPPLEMENT	
ERROR E	INVALID OWNERSHIP STATUS CODE	
ERROR F	INVALID FOUNDATION TYPE	
ERROR G	INVALID CONDITION STATUS CODE	
ERROR H	INVALID CONSTRUCTION STATUS CODE (TYPE STRUC)	
ERROR I	INVALID AIR CONDITIONED STATUS CODE	
ERROR J	INVALID HEATING STATUS CODE	
ERROR K	INVALID FLOOR STRUCTURE STATUS CODE	
ERROR L	INVALID ROOF STRUCTURE STATUS CODE	
ERROR M	INVALID EXTERIOR WALL FINISH CODE	
ERROR N	INVALID ROOF MATERIAL STATUS CODE	
ERROR O	STATE IDENTIFICATION NUMBER IS BLANK	1
ERROR P	GROSS AREA = ZEROS OR BLANK	
ERROR Q	CONSTRUCTION DATE PRIOR TO 1800 OR BLANK	
ERROR R	BLDG IS OWNED BUT NO BOOK OR ESTIMATED VALUE IS PROVIDED	
ERROR S	NET ASSIGNABLE SQ FT + CUSTODIAL, CIRCULATION MECHANICAL > GROSS SQUARE FEET THE SUM OF THE NET SQ FT OF THE ROOMS IN THIS BUILDING IS GREATER THAN THE REPORTED GROSS SQ FT	
ERROR T	NET ASSIGNABLE SQUARE FEET = ZEROS OR BLANK (NO ROOMS ASSIGNED TO THIS BUILDING OR BUILDING CONTAINS ONLY ROOMS WITH ROOM TYPES OF 010, 020, OR 030)	
T O T A L S		
TOTAL NUMBER OF BLDGS (MATCHED)		2
TOTAL ERRORS		1
TOTAL BOOK VALUE OF BLDGS (IN THOUSANDS)		12307
TOTAL EST VALUE OF BLDGS (IN THOUSANDS)		2640
TOTAL GROSS AREA OWNED BY INST.		69638
TOTAL GROSS AREA LEASED BY INST.		
TOTAL GROSS AREA		69638

\*\* PLEASE REFER TO THE FACILITIES MANUAL TO OBTAIN THE CORRECT CODES.