

BLDGS EDIT-Z235B259  
 FALL DATA 2007  
 RUN DATE 03/19/2008  
 PAGE NUMBER 1

L.T.C.-NORTHEAST  
 BRANCH  
 PARISH  
 RELATION OTHER

| ERRORS | NO.  | -----B U I L D I N G-----<br>NAME STATUS<br>& STATE ID      | -----SQFEET<br>NET | AREAS-----<br>GROSS | -----DATES OF-----<br>CNST RENOV. | BOOK VALUE--<br>BLDG.<br>(000) | REPLACE.<br>V/BLDG.<br>(000) | NO. OF<br>FLOORS |
|--------|------|---|--------------------|---------------------|-----------------------------------|--------------------------------|------------------------------|------------------|
|        | 000A | Business, Welding, OWNED BY INST.<br>SATISFACTORY<br>S08651 | 10,004             | 12,647              | 1952                              | 309                            | 677                          | 1                |
|        | 000B | Admissions, Testin OWNED BY INST.<br>SATISFACTORY<br>S08652 | 1,339              | 1,672               | 1952 1999                         | 41                             | 92                           | 1                |
|        | 000C | Student Lounge, Ma OWNED BY INST.<br>SATISFACTORY<br>S08653 | 1,408              | 4,800               | 1975 1999                         | 74                             | 229                          | 1                |
|        | 000D | Administration, LP OWNED BY INST.<br>SATISFACTORY<br>S08654 | 7,758              | 11,088              | 1975 1999                         | 219                            | 623                          | 1                |

BLDGS EDIT-Z235B259  
FALL DATA 2007  
RUN DATE 03/19/2008  
PAGE NUMBER 2

L.T.C.-NORTHEAST  
BRANCH  
PARISH  
RELATION OTHER

D E S C R I P T I O N A N D S U M M A R Y O F E R R O R S

ERROR A DUPLICATE BLDG  
ERROR B DUPLICATE SUPPLEMENT  
ERROR C UNMATCHED BLDG  
ERROR D UNMATCHED SUPPLEMENT

ERROR E INVALID OWNERSHIP STATUS CODE  
ERROR F INVALID FOUNDATION TYPE  
ERROR G INVALID CONDITION STATUS CODE  
ERROR H INVALID CONSTRUCTION STATUS CODE (TYPE STRUC)  
ERROR I INVALID AIR CONDITIONED STATUS CODE  
ERROR J INVALID HEATING STATUS CODE  
ERROR K INVALID FLOOR STRUCTURE STATUS CODE  
ERROR L INVALID ROOF STRUCTURE STATUS CODE  
ERROR M INVALID EXTERIOR WALL FINISH CODE  
ERROR N INVALID ROOF MATERIAL STATUS CODE  
ERROR O STATE IDENTIFICATION NUMBER IS BLANK

ERROR P GROSS AREA = ZEROS OR BLANK

ERROR Q CONSTRUCTION DATE PRIOR TO 1800 OR BLANK  
ERROR R BLDG IS OWNED BUT NO BOOK OR ESTIMATED VALUE IS PROVIDED  
ERROR S NET ASSIGNABLE SQ FT + CUSTODIAL, CIRCULATION MECHANICAL > GROSS SQUARE FEET  
THE SUM OF THE NET SQ FT OF THE ROOMS IN THIS BUILDING IS GREATER THAN THE REPORTED GROSS SQ FT

ERROR T NET ASSIGNABLE SQUARE FEET = ZEROS OR BLANK (NO ROOMS ASSIGNED TO THIS BUILDING OR BUILDING CONTAINS ONLY ROOMS WITH ROOM TYPES OF 010, 020, OR 030)

T O T A L S

|  |       |
|--|-------|
| TOTAL NUMBER OF BLDGS (MATCHED)          | 4     |
| TOTAL ERRORS                             |       |
| TOTAL BOOK VALUE OF BLDGS (IN THOUSANDS) | 643   |
| TOTAL EST VALUE OF BLDGS (IN THOUSANDS)  | 1621  |
| TOTAL GROSS AREA OWNED BY INST.          | 30207 |
| TOTAL GROSS AREA LEASED BY INST.         |       |
| TOTAL GROSS AREA                         | 30207 |

\*\* PLEASE REFER TO THE FACILITIES MANUAL TO OBTAIN THE CORRECT CODES.